

**IN THE UNITED STATES PATENT & TRADEMARK OFFICE**

ATTORNEY DOCKET NUMBER: 200314830-1

IN RE APPLICATION OF: U.S. Patent No. 7,613,950

USPTO CONFIRMATION CODE: 8425

APPLICATION NO.: 10/789,733

FILED: Feb. 27, 2004

EXAMINER: ELMIRA MEHRMANESH

GROUP ART UNIT: 2113

FOR: DETECTING FLOATING POINT HARDWARE FAILURES

**37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION**

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

Sir:

The following is a request for a certificate of correction in Serial Number 10/789,733, now Patent Number 7,613,950.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

All errors were the fault of the USPTO, no fee required. In the event that a further fee is required, please charge the amount to Deposit Account No. 082025.

All errors were the fault of the applicant and, accordingly, please charge **\$100.00** to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The errors were the fault of both the applicant and USPTO and, accordingly, please charge **\$100.00** to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

In column 7, line 15, in Claim 3, delete "DEL" and insert - - DFL - -, therefor.  
(Amendments to claims filed on Mar. 19, 2009, page 2, in claim 3, line 3)

In column 7, line 33, in Claim 8, delete "DEL" and insert - - DFL - -, therefor.  
(Amendments to claims filed on Mar. 19, 2009, page 3, in claim 8, line 3)

In column 8, line 10, in Claim 15, delete "DEL" and insert - - DFL - -, therefor.  
(Amendments to claims filed on Mar. 19, 2009, page 5, in claim 15, line 3)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

March 17, 2010  
DATE

/David A. Plettner/  
Name: David A. Plettner  
Registration No.: 36,241

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY  
Intellectual Property Administration  
3404 E. Harmony Road  
Mail Stop 35  
Fort Collins, CO 80528

**UNITED STATES PATENT AND TRADEMARK OFFICE**  
**CERTIFICATE OF CORRECTION**

Page 1 of 1

PATENT NO. : 7,613,950

APPLICATION NO. : 10/789,733

ISSUE DATE : Nov. 3, 2009

INVENTOR(S) : John W. Curry

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 7, line 15, in Claim 3, delete "DEL" and insert - - DFL - -, therefor.

In column 7, line 33, in Claim 8, delete "DEL" and insert - - DFL - -, therefor.

In column 8, line 10, in Claim 15, delete "DEL" and insert - - DFL - -, therefor.

**MAILING ADDRESS OF SENDER (Please do not use customer number below):**

Hewlett-Packard Company  
Intellectual Property Administration  
3404 E. Harmony Road  
Mail Stop 35  
Fort Collins, CO 80528

This collection of information is required by 37 CFR 1.322, and 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Box 1450, Alexandria, VA 22313-1450.